


CENTURY MINE MITIGATION STREAM MITIGATION PHOTOGRAPHS
Long Run



Photograph: 62
LRL-2: Partially successful restoration of stream bank



Photograph: 63
LRL-3: Unsuccessful coir log




Photograph: 64
LRL-4: Unsuccessful coir log



Photograph: 65
LRL-5: Failed step pool complex



Photograph: 66
LRL-5: Failed step pool complex



Photograph: 67
LRL-6: Partially successful coir mat and live staking